G. R. S. 59] GPB—15 000 20 12 13

GENERAL AND REVENUE SECRETARIAT.

1894-5
191.
(Inwrai)

File No. 73

Serial Nos.

Papers Filed.

*Month*_____

SUBJECT.

Sanctioning an Estimate for Rs 8981-8- for repairing the Narasimhaswamy Temple Tonnur, Srirangapatam Taluk.

PREVIOUS REFERENCES LATER REFERENCES

Thondaman
14/9/95

Respected Sir,

Leaving a return screening
[illegible] early - some
laundry work, not provided
in the estimate, but found
necessary during execution,
have been carried out. The
estimate is distributed under
the above heading has been
kept to the minimum with the
exception of [illegible]
which [illegible] £150
Items left off [illegible] are this

as

returns, this
is well, to complete the Victoria
Building and give a good
visit but I could not
do so without transition.

I came here on the 8th
evening as described for
the Evening Institute
but one does not get on
most here invariably
I am coming here.

I beg you will excuse this
change in this letter this
and

Measurements of Work Done to Varatharaja Swamy's Temple (Sengry Kovil) at Tondanoor

Taluk Seringapatam

Details of Work	No.	Dimensions L	B	Contents	Total
th 2 Courses at					
Ells and P					
North and South	1	34	10½	"	357	
West or Rear Side	1	41½	11	"	457	
Do	1	18	13		234	
Hall	1	43	31	"	1333	
Front Side	1	9½	7½	"	71	
Total					2452	
Deduction						
Ventilator of Kitchen	1	8¾	2½	"	22	
Bal				Sqr		24·30
Brick in Chunam						
Parapet Walls on the roof						
North & South	2	52	1/8	2¼	263	
East & West Side	2	44	1/8	2¼	223	
Sides in Front	2	10	1/8	2¼	51	
Walls of Ventilator	2	8¾	1/8	4	79	
Do	2	2½	1/8	4	23	
over Slabs	1	9	5¼	½	24	
Walls of Bhaagatkar	1	13½	1/8	8	122	
Do	1	8½	1/8	7¼	69	
Total					854	
Deductions Windows of	2	4¾	1/8	½	16	
Windows of Bhaag	1	4½	1/8	4½	23	
Do Do	1	6½	3½	2	20	
Total D					62	

m - 7 2

Plastering with Chunam

Parapet Wall on the roof	1	212	5 3/4	.	1219	
Sides at the Opening between Roofs	2	34	2	.	136.	
Do Do	2	18	1 3/4	.	63.	
Top of Ventilator	1	9 3/4	6		59	
Sides of Door all round	1	27	2	.	54	
Bhaayakar Sammidy	1	22	7 3/4	.	171	
Do out Side	1	24 3/4	7 1/2	.	186.	
Kitchen Walls of both Sides	2	19	7	.	266	
Do Cross Walls	2	7 1/2	8	.	120	
Fire place in the Kitchen	1	7.	2 3/4	.	19	
Floor of Kitchen	1	16	7	.	112	
In Side of Ventilator	1	15	4	.	60.	
Floor of Verandah	1	34	4	.	136.	
Door - Way	1	7	3 1/2	.	25	
Total					2626	

Deductions

Windows of Kitchen	2	4 3/4	1 1/2		14	
Door of Bhaayakar Samm	1	4 1/2	4 1/2		20.	
Do Do	1	6 1/2	3 1/2	.	23	
Total Deductions					57	
Balance Chunam Plastering					Sqr	2569.

Burnt Brick in Mud

Side Wall	1	19	1 1/8	7 1/2	160	
Cross Wall	1	7 1/2	1 1/8	8	67 1/2	
Fire place	1	7	2 1/8	2	31 1/2	
Total Burnt Brick in Mud					cft	259.

Concreat Work						
floor of Kitchen	1	16	7	1/2	56	
Over the wall' jinto the hole						
' leaks at the palace where						
all had ban.	1	20	5	1/2	150 / 50	
to kitchin., (for which Le S ~~to~~						
has been provoded in the Est.						
" Over the ~~roof~~ to get	1	43	31	1/4	333 / ~~333~~	
	Co		ork		Cft	587 / ~~438~~
New Slabs						
Over the Ventilator of	2	9	2 1/2	1/2	22 1/2	
Tot	.	w	abs		Cft.	22 1/2
Old Slabs for putting on the roof	1	4	2	1/2	9	
Tot						
Cornice over parapet Wall	1	212	-	-	Rft.	212
Teak wood Shutters with						
bars &c. Complete	1	6 1/4	4 1/4	.	26 1/2	
" Bhasyakars Temple	1	6 1/2	3 1/2	.	22 3/4	
" Windows with iron bars,						
" Wooden Shutters &c. Comp	1	4 1/2	4 1/2	.	20 1/4	
" Outer Door	1	7	5 1/4	.	36 3/4	
" Windows of kitchin	2	4	1 1/2	"	12	
	So				Sft	118 1/4
Pointing with mortar						
Sides	2	46	11		1012	
Do	2	78	11	.	1716	
Gate Way	1	8	9		72	
	Total				Sqr.	28.00

White Washing

Veeran temple	1	17	30	.	510	
Do	2	63	8½	.	1054	
Bhagyakar Sannidhy	2	13	8	.	208	
Do	2	9	8	.	144	
Roof	1	13	9	.	117	
Total White Washing					Sqs	20:33.
Removing roots all round the Temple		Lump	Sum		Rupees	15
Repairing Steps in front		Lump	Sum		Rupees	30

Anuslan Kola

Ribbon laying the pavement	1	18	3	8	432	
Do	1	21	3	8	504	
Steps	1	10	3	4	120	
Total Stone Work					Cyds	39

Anuslan Mantapam

Roofing with 2 Courses of flat tiles & Chunam plaster	1	18	10	.	180	
Total					Sqs	1·8
Cornice	1	56			Rft	56.
Brick in chunam						
Parapet Wall	1	50	1½	½	28	Sft. 28
Plastering & white chunam	1	50	1½	.	75	Sqs 75
Pointing	1	32	11	.	352	
Do	1	21	7	.	147	
Total Pointing						4·99

Abstract or Bill for Payment for Work done by Contractor Veerabhadra Iya of Sirnjapatam

01 16 1955

Items of Work	No	Rate Rs	Rate as	Rate p	Quantity	Cost Rs	Cost as	Cost p
Roofing with 2 Courses of flat tiles and Chunam Plaster	Sqr	10	.	.	24 30	243	-	-
Brick in chunam	Cft	.	3	-	792	148	8	.
Plastering with Chunam	Sqr	2	4	.	25 69	64	3	7
Burnt Brick in mud	Cft	-	1	9	259	28	5	3
Concreat Work	Cft	.	2	6	53 438	84 68	3	0 -
Slabs Stones new	Cft	-	12	-	22½	16	4	-
Do old	Cft		4	-	9	2	4	-
Cornice	Rft	-	4	-	213	53	-	-
Teak Wood Shutters with Iron bars &c. Complete	Sft	1	2	.	118¼	133	-	6
Pointing with mortar	Sqr	1	-	-	28 00	28	-	-
White Washing	Sqr	-	3	-	90 33	3	12	11
Removing roots all round the	Lump Sum				Rupees	15	-	-
Repairing Steps in front	Lump Sum				Rupees	30	-	-
Anustan Kola								
Old Stone Work	Cydo	-	8	-	39	19	8	-
Anustan Munthapum								
Roofing with 2 Courses of flat tiles & Chunam Plastering	Sqr	10		-	1 5	18	-	-
Cornice	Rft	-		-	56	14	-	-
Brick in chunam	Cft	-	5	-	28	5	4	

Anusham mantapam (Continued)

Plastering with Chunam	Lgr	2 . 8	-75	1	14
Pointing with Mortar	Lgr	1 12	4·99	8	11 -8
Total Rupees					917- 9- 5

(A Rama Krishna Rao
Volunteer O.C.W
A.E. II S.D.
Nagamangala

(Illegible)

Signature of Contractor

Government of Mysore ——————————————— Dr.

Particulars	Amo	Remarks
To The amount of actual cost of work done upto date to the Narsimha Swami temple at Sonnur in the Serangapatam Taluk. ——————— Rupees nine hundred and seventeen annas nine and pies five only. (To be made payable at the Serangapatam Taluk Treasury	917 9 5	The amount to be met as specified below:— Rs. 898-4-4 from the State for 1894-95 vide Govt. Pro: No. 1058 dy 29th May/95. Rs. 19-9-5 from do-do for 1895-96 vide Govt. Pro: No. dy Sept/95
	917-9-5.	

Bangalore
Sept/95.

Murgai Supdt.
6 75

No: 1053 dy 29/31/5/95 Ery

Order.

The accompanying estimate for Rs. 898 to repair the Narasimhaswamy Temple in Tonnur Srirangapatam Taluk, which has been prepared after a personal inspection of the temple by the Supervisor of the Mysr-Dept, is sanctioned, the Charge being met from the State of Rs 13000 Sanctioned in Govt Proc no. 996 Mysr-~~1105~~-92 dy 24th March 1894 for the repairs of Mysr asai Institutions in the Province during the year 1894-5-

Gen. Serial No. 30.]

189

MUZARAI.

2. The amount sanctioned referred to in the foregoing para will be paid on presentation of the Completion of a bill duly signed by the Mus-Supt.

By order

WS

Secy

To The Completion Supt.

From

The Secretary to the
Dewan of Mysore.

To

Dated

Despatched

Received

Enclosures No.

General No.
Muzarai F. No.

M.G.C.P.B.—21-6-94—1,000.

Read

Govt. Pro: No. 1055 dated 29th May/95 sanctioning an estimate amounting to Rs. 898/ to repair the Narasimha Swami temple at Bommur Gerangapatam Taluk.

Order thereon --

R

No. 4549 19-9-95

Encl.

Mr. G. Surya Narain Rao who was deputed to supervise the work of the aforesaid temple reports that the work has been satisfactorily completed, that during the course of execution some additional sundry works were found absolutely necessary and that they have been carried out and requests that the payment of the additional charges

excess outlay of
Rs. 19-9-5 may be
sanctioned.

2. Under the circumstances reported the payments of the excess outlay of Rs. 19-9-5 is sanctioned the charge being met from the state grant of Rs. 15000 sanctioned in Govt Pro: No. 749 M.E. 105-92 dated 25th June 1895 for the repairs of Mutts and institutions in the Province for 1893-96.

3. The amount originally sanctioned in the Govt Pro: cited above for the repairs of the Narasimha Swami temple at Sonnur from the state grant for 1894-95 is Rs. 898/.

The excess outlay now sanctioned hereby from the State grant for 1895-96 is Rs 19-9-5 thus, the whole cost amounts to Rs. 917-9-5. A bill for this amount is prepared and forwarded to the Comptroller for audit and return to the Nazrai Suba for payment at once. The amount should be made payable at the Seringapatam Taluk Treasury.

4. A copy of the abstract measurement of work on which the bill is based will also be forwarded to the Comptroller.

By order
Secretary.
L.S.

To The Comptroller
to the Govt of Mysore
with the bill and a
copy of the abstract measurement